

Inserire sul cavo
M21.013+M21.101 siglato A1
M21.013+M21.101 siglato B1
M21.013+M21.101 siglato A2
M21.013+M21.101 siglato B2
M21.013+M21.101 siglato A3
M21.013+M21.101 siglato B3
M21.013+M21.101 siglato A4
M21.013+M21.101 siglato B4
M21.013+M21.101 siglato A5
M21.013+M21.101 siglato B5
M21.013+M21.101 siglato A6

X1							FUNCTION
H33068							GROUND
FRUTTO PRESA 24P+T ILME S.CDD							GROUND
Pin	ID	Nr	Sez	Cross	L (mm)	Contatto	
1	B		2.5	X0/1	2330	H33068.3	GROUND
2	B		2.5	X0/1	2330	H33068.3	GROUND
3	H	1	1	SA1/1	570	H33068.1	RAISE RIGHT HAND RAKE WHEELS
4	H	1	1	SA1/3	570	H33068.1	LOWER RIGHT HAND RAKE WHEELS
5	H	2	1	SA2/3	640	H33068.1	CLOSE RIGHT HAND FRAME ANGLE
6	H	3	1	SA2/1	640	H33068.1	OPEN RIGHT HAND FRAME ANGLE
7	H	4	1	SA3/1	640	H33068.1	OPEN FRAME
8	H	5	1	SA3/3	640	H33068.1	CLOSE FRAME
9	H	6	1	SA4/3	640	H33068.1	CLOSE LEFT HAND FRAME ANGLE
10	H	9	1	SA4/1	640	H33068.1	OPEN LEFT HAND FRAME ANGLE
11	H	7	1	SA5/1	570	H33068.1	RAISE LEFT HAND RAKE WHEELS
12	H	10	1	SA5/3	570	H33068.1	LOWER LEFT HAND RAKE WHEELS
13	H	8	1	S2/-	630	H33068.1	BY PASS BLOCK VALVE
14	C		1	S1/-	580	H33068.1	AUXILIARY CIRCUITS
15	N		1.5	X0/2	2330	H33068.2	IDENTIFICATION, CLEARANCE & SIDE MARKERS
16	L		1.5	X0/3	2330	H33068.2	LEFT HAND TURN SIGNAL
17	M		1.5	X0/6	2330	H33068.2	TAIL, CLEARANCE & SIDE MARKER LAMPS
18	R		1.5	X0/4	2330	H33068.2	STOP LAMPS
19	Z		1.5	X0/5	2330	H33068.2	RIGHT HAND TURN SIGNAL
20							
21							
22							
23							
24							

