

Product BULLETIN

NUMBER: T0077

DATE: 12 Oct 2016

AFFECTED PRODUCT: Boss II

Current production of the Bale Boss II now features a chain coupler to drive the beaters. This will allow for slight misalignment between the motor and the beater shaft, reducing mounting flange fatigue and undesirable motor movement.

Units in the field can be changed, if desired, by removing the fixed coupler and installing the chain coupler.

