







PARTS

OBSOLETE BEARINGS

Studs Bolts will be 5/8



15



30

PARTS FOR S-46B BEARING

1. B4 Hub Cap
2. B2A Self Locking Nut
3. B3A Flat Washer
4. B11B Small Cone
5. B11A Small Cup
6. B9 Cast Iron Hub
7. B10B Large Cone
8. B10A Large Cup
9. B8 Grease Seal
10. B5B Spindle
11. C12B Dust Cap
12. C13 Bracket
13. C2A Self Locking Nut
14. B1 Zerk Connection
15. S46A Complete Bearing

PARTS FOR S-47B BEARING (Heavy Duty)

16. C1 Zerk Connection
17. C2A Self Locking Nut
18. C13 Bracket
19. C12 Dust Cap
20. C5B Spindle
21. C8 Grease Seal
22. C10B Large Cone
23. C10A Large Cup
24. C9 Cast Iron Hub
25. C11B Small Cone
26. C11A Small Cup
27. C3A Flat Washer
28. C2A Self Locking Nut
29. C4 Hub Cap
30. S-47 Complete Bearing (Heavy Duty)